






Outlast Fabric Washing Instructions

	Machine Wash at 40°C or less on a reduced cycle.
	Do not bleach.
	Garment can be tumble dried at low setting.
	Garment can be ironed at maximum temperature of 110°C.
	Gentle wet cleaning.

For any queries regarding cleaning of the cooling sheet, please contact Medifab at the details below:

solutions@medifab.com
www.medifab.com

Manufacturer of


HEAD OFFICE

32 Detroit Dr, Rolleston
 Christchurch 7675
 Ph +64 3 307 9790
 Fax +64 3 307 2820

AUCKLAND

277 Mt Smart Rd
 Penrose
 Auckland 1061
 Ph +64 9 589 0890

AUSTRALIA

26 Pardoe St
 Devonport
 TAS 7310 Australia
 Ph +61 3 6427 0105